ME7 Manometer for highly excessive pressures

Ø 150 mm

Bellows pressure gauges For corrosive process fluids and atmospheres Watertight, can be filled with dampening fluid



The **ME** pressure gauge enables measurement of gauge pressures with high overpressures (from 0...0.06 bar to 0...10 bar).

Specifications (20°C)

Ranges	See tables overleaf.				
Accuracy	± 2% full scale for st. graduations and accuracy (see table overleaf) BH version: Degradation of the accuracy of 1%				
Protection rating	IP 65 according to EN 60529.				
Sensing element	Two 1.4404 (AISI 316 L) stainless steel bellows. Balance effect by high tensile leaf spring ; mechanical start and end-of-travel stops to withstand full static pressure.				
Connections and parts in contact with process fluid	1.4401 (AISI 316 L) stainless steel. G 1/2 or 1/2 NPT threads				
Gauge working temperature	-2070° C The gauge may be used on fluid temperatures up to 200°C providing that the gauge tempera- ture does not exceed 70°C.				
Case and Bezel ring	1.4301 (AISI 304) stainless steel. Bayonet lock type.				
Window	Glass, 3 mm thick.				
Window gasket	Elastomer, ensures a tight seal between glass window and case.				
Movement	All stainless steel.				
Dial	Aluminium alloy, black figures and graduations on white background.				
Pointer	Aluminium alloy, balanced, black painted.				
Blow-out disc	Elastomer. Positionned on the top of the pressure gauge.				
	Ensures pressure balance with atmosphere. Blows out when pressure inside the case exceeds 0.6 bar (10 psi).				
Weight	1.6 kg ("dry" gauge) 2.5 kg (filled with dampening liquid)				

Options

Adjustable index pointer with polycarbonate window	Code 0052
Polylethacrylate glass (plexiglass)	Code 0752
Safety laminated glass	Code 0751
Hardened glass	Code 0756
Oxygen Application	Code 0765
Laboratory cleanliness	Code 0835
or nuclear cleanliness	Code 0838
Micrometric pointer*	Code 0678
Pointer adjustable by friction*	Code 0679
Version ATEX C€ II 2 GDc - I M2c avec voyant triplex.	Code 0078
Threads smaller than or equal to G1/2	

* except reduced scales



www.baumer.com/process

Dimensions (mm) - Types of mounting



TYPE B or C

Type B

145 3 maxi

Panel cut-out





20

Ordering details - ME7

		ME7xxxxxxx
Family	1´digit	
Pressure gauges		M
Туре	2´ digit	
ME		E
Dial diameter	3´ digit	
Ø 150 mm		7
Type of mounting* and connections position	4´ digit	
bottom connection, 3 fixing brackets rear back connection, front flange bottom connection, front flange bottom connection back connection back connection * <i>Option Stainless steel 1.4404 (316L) change A with 1, B w</i> <i>4, E with 5 and F with 6</i>	ith 2, C with 3, D with	A B C D E F
Pressure connection	5´ digit	
G 1/2	U	3
1/2 NPT		6
Type of liquid filling	6´ digit	
Without BH1 filling (low viscosity glycerin)		0
BH2 filling (flight viscosity glycerin)		2
BH4 filling (low temperature silicone oil)		4
BH5 filling (fluorinated oil)*		5
BH7 filling (oil compatible with freezing fluids)		7
* Only with pressure gauge oxygen degreased (P max. 160 k	oar)	
Unit of measurement	7´ digit	1111
bar		В
kPa		D
kg/cm2		F
psi		H
Pressure range 8	3´9´ digit	
See codes in table		XX
Overpressure (bar)	10´ digit	
See codes in table		х

Choose an excess pressure scaling as a function of relative pressure (ME) and the maximum excess pressure that the apparatus can sustain.

ME			Overpressure										
Code	Gauge pressure	0,6	1	1,6	2,5	4	6	10	16	25	40	60	100
07	0 + 0.06	\otimes	\otimes	۰	۰								
08	0 + 0.1	\otimes	\otimes	\otimes	•	•							
09	0 + 0.16	*	*	*	*	\otimes	\otimes						
10	0 + 0.25	*	*	*	*	*	\otimes	\otimes	•				
11	0 + 0.4	*	*	*	*	*	*	\otimes	\otimes				
12	0 + 0.6		*	*	*	*	*	*	\otimes				
15	0 + 1			*	*	*	*	*	*				
16	0 + 1.6				*	*	*	*	*	*			
18	0 + 2.5					*	*	*	*	\otimes	\otimes		
19	0 + 4						*	*	*	*	*		
20	0 + 6							*	*	*	*		
22	0 + 10								*	*	*	*	
	Code	A	С	D	Ε	F	G	Н	J	Κ	L	М	Ν



Standard accuracy \leq 4 %